

# ***ILLINOIS***

***DEPARTMENT OF NATURAL RESOURCES***



## **RECREATIONAL BOATING ACCIDENT REPORT 2009**

Compiled by Federal Fiscal Year 2009  
Updated: February 15, 2010



## FOREWORD

Recreational Boating Accident Report 2009 contains statistics on recreational boating accidents, recreational boating enforcement, boating safety, and boat registering activities. Statistical information contained in this report is based on the Federal Fiscal Year 2009 (FFY09) (10/01/2007 – 09/30/2008), excluding the registered boats, which is based on calendar year 2009. This publication is a result of the coordinated effort of the Illinois Department of Natural Resources (IDNR) and those jurisdictions which investigate recreational boating accidents and enforce boating laws in the State of Illinois.

Recreational Boating Accident Report 2009 may be copied freely in the interest of boating safety. For questions and suggestions regarding content, availability of the current or back issues, use the address or telephone number at the top of this page. For an electronic copy, visit the Illinois Department of Natural Resources Web Site at <http://dnr.state.il.us/law3/>

### Law Enforcement Creed

*“To serve, protect, and educate the citizens and visitors to the state of Illinois in their outdoor recreational endeavors.”*

*“To be a vigilant guardian of the natural resources, public safety, and homeland security of Illinois.”*

*“To assist the public in their times of need; routine and emergency.”*

*“To educate the inadvertent violator of conservation law, by taking an appropriate level of enforcement action to achieve this goal.”*

*“To relentlessly pursue, with full statewide police authority, deliberate offenders and bring them before the courts for the administration of justice”*

*“To maintain the highest level of professional standards, integrity, and conduct.”*

*“THIS WE PLEDGE TO THE CITIZENS OF ILLINOIS.”*



Captain Joe Morelock  
Illinois Boating Law Administrator

# TABLE OF CONTENTS

Introduction	5
Scope	5
Use of the Statistics	5
Accidents Excluded from the Report	6
Accidents That Are Included in This Report	6
Boating Accidents and Enforcement at a Glance	7
Boating Safety Education	8
Traditional Course	8
Boat-Ed Internet Course	8
Reporting Guidelines for Boat Accidents	9
Non-Reportable Guidelines	10
Registered Recreational Boats	11
Report of Certificates of Number Issued to Boats	11-12
Total Number of Registered Boats – 2000 - 2009	13
Total Number of Registered Boats Not Mechanically Propelled – 2000 - 2009	13
Boating Statistical Summary	14
<b>BOATING ENFORCEMENT – Federal Fiscal Year 2009</b>	<b>15</b>
Top Boating Violations	15
Top Citations	15
Top Written Warnings	15
Boat Registration Inspections	16
Operating Under the Influence (OUI) Arrests	16
Boating Accidents and Alcohol Use	17
<b>BOATING ACCIDENT REPORT – Federal Fiscal Year 2009</b>	<b>18</b>
Total Number of Accidents	18
Total Number of Injuries	18
Total Number of Fatalities	18
Total Number of Vessels	18
Total Number of Registered Boats	18
Number of Accidents per 100,000 Registered Boats	18
Number of Injuries per 100,000 Registered Boats	18
Number of Fatalities per 100,000 Registered Boats	18
Cause of Death	18
Victim Activity	18
Use of Personal Floatation Device (PFD)	18
Primary Type of Injury	18
Injury Causes	

Accident Statistics by Day of Week	19
Accident Statistics by Month of the Year	19
Accident Statistics by Time of Day	19
Accident Statistics by Water Conditions	20
Accident Statistics by Weather Conditions	20
Accident Statistics by Wind Conditions	20
Accident Statistics by Visibility	21
Accident Statistics by Primary Cause of Accident	21
Accident Statistics by Type of Accident	22
Accident Statistics by Vessel Length in Feet	22
Accident Statistics by Type of Boat	23
Accident Statistics by Operation at Time of Accident	23
Accident Statistics by Operator Education	24
Accident Statistics by Operator Experience	24
Accident Statistics by Operator Age	24
Accident Statistics by Body of Water	25
Accident Statistics by Body of Water Broken Down by County	26,29
Accident Statistics by County	30
Accident Statistics by County Broken Down by Body of Water	31-34
Boating Accident Fatality Narratives	35-41
Glossary of Boating Terminology	42-45



# INTRODUCTION

## SCOPE

Statistical information contained in this report is based on the Federal Fiscal Year 2009 (FFY09) (10/01/2008 – 09/30/2009), excluding the registered boats, which is based on calendar year 2009. This report contains statistics on recreational boating accidents, registered boats, boating enforcement, and information on boating safety activities. Data used to compile the recreational boating accident statistics comes from two sources: (1) Boating Accident Reports of IDNR investigations of boating accidents that occurred on waters within the State; and (2) reports forwarded to the IDNR by other jurisdictions within the State. In the absence of investigations, information is collected from accident reports filed by boat operators. Data used to compile the boating enforcement statistics comes from three sources: (1) IDNR Conservation Police Officer Daily Activity Reports, (2) CPO Operating Under the Influence Reports, and (3) reports forwarded to the IDNR by other jurisdictions within the State.

## USE OF THE STATISTICS

Users of the statistics in this report need to be aware of the following facts that may affect results of analyses of accident report data:

1. Some accidents are not in the system because they are not required to be reported. Many more accidents are not reported because boaters are not aware of the accident reporting regulations as well as the difficulty law enforcement agencies encounter in enforcing those regulations. We believe only a small fraction of boating accidents occurring in the State of Illinois are not reported to the IDNR or local law enforcement agencies. However, we believe nearly all fatal recreational boating accidents are included in this report. Overall, the more serious the accident, the more frequent the reporting.
2. Non-fatal accidents cannot be assumed to have occurred in numbers proportional to the reported statistics because the act of reporting an accident is not a random sampling of accidents in the statistical sense. Rather, selection is based on the ability and willingness of those involved to file a report.
3. Fluctuations from year to year in statistics may be caused by factors other than the change in the total number of recreational watercraft. A seemingly small change in the low reporting rate may cause a relatively large change in the statistics.
4. Recreational boating enforcement is not a random sampling of arrests in the statistical sense. Rather, selection is based on arrests the Conservation Police and other law enforcement agencies involved report to the IDNR.

## ACCIDENTS EXCLUDED FROM THE REPORT

This report does not include the following:

1. Accidents involving only property damage of less than \$2000;
2. Accidents involving only slight injury which did not require medical treatment beyond first aid;
3. Accidents which were not caused or contributed to by a vessel, its equipment, or its appendages;
4. Accidents where a person died or was injured from natural causes while aboard a vessel;
5. Accidents where a person died or was injured while swimming to retrieve an object or a vessel that was adrift from its mooring or dock, having departed from the shore or pier;
6. Accidents involving damage, injury, or death on a docked or moored vessel that resulted from storms, or swell conditions
7. Accidents where a person died or was injured while swimming for pleasure from a vessel that WAS NOT underway (i.e., the vessel was anchored, moored, or docked). In those cases, the vessel was being used as a platform for other activities, such as swimming or diving, and was not involved in any event that contributed to the casualty.

## ACCIDENTS THAT ARE INCLUDED IN THIS REPORT

This report includes the following boating accidents involving a swimmer, a recreational vessel and its operation:

1. A person dies or is injured while swimming because of carbon monoxide poisoning;
2. A person dies or is injured while swimming because a vessel is improperly connected to shore power and resultant stray electrical current enters the water causing electrocution;
3. A person dies or is injured after leaving a vessel that is underway to swim for pleasure because the vessel IS NOT anchored, moored, or docked and the swimmer is unable to get back to the vessel;
4. A person is struck by a vessel, or its associated equipment, where the vessel serves as the instrument striking the person.

Accident reports for twenty-five (25) fatalities were entered into the IDNR System that satisfy the reporting requirements above for inclusion in this report.

## BOAT ACCIDENTS & ENFORCEMENT AT A GLANCE

Year	Total Number of Accidents	Total Number of Injuries	Total Number of Fatalities	Total Number of Vessels	Total Number of Registered Boats	Number of Fatalities per 100,000 Registered Boats	Total Number of Fatalities by Drowning	Conservation Police Operating Under The Influence (OUI) Arrests	Total Number of Boating Citations	Total Number of Boating Written Warnings	Total Hours Worked on the Recreational Boat Safety Program (RBS)
1993	134	94	32	163	371,000	8.6	29	57	0	0	0
1994	157	131	17	211	381,864	4.5	15	67	0	0	0
1995	178	88	16	228	386,500	4.1	13	111	0	0	0
1996	155	90	27	214	390,000	6.9	23	93	0	0	0
1997	145	81	14	223	397,000	3.5	10	123	0	0	14,328
1998	176	107	19	249	395,500	4.8	12	75	0	0	16,048
1999	159	75	13	238	394,108	3.3	10	96	0	0	13,822
2000	155	76	14	231	370,568	3.8	11	101	0	0	11,869
2001	112	75	8	171	368,047	2.2	7	181	2,263	0	13,185
2002	135	92	23	188	364,075	6.3	13	200	1,630	0	13,369
2003	84	63	13	122	360,252	3.6	7	125	0	0	10,827
2004	78	45	18	103	356,305	5.0	15	127	1,509	1,647	13,858
2005	115	100	16	152	342,745	4.7	12	185	1,403	0	15,046
2006	79	66	18	119	343,591	5.2	13	229	1,882	3,307	15,866
2007	107	57	13	146	339,288	3.8	11	144	1,451	3,239	30,332
2008	120	78	13	174	336,025	3.9	10	154	1,603	3,695	39,998
2009	102	70	25	137	329,032	7.6	14	179	1,960	5,567	21,403
<b>Total</b>	<b>2191</b>	<b>1388</b>	<b>299</b>	<b>3069</b>	<b>6,225,900</b>	<b>4.8</b>	<b>225</b>	<b>2247</b>	<b>13,701</b>	<b>17,455</b>	<b>229,951</b>

\* In 2003, Coast Guard's reporting criteria for property damage went from \$500 to \$2,000.

\* In 2006, IDNR's reporting criteria for property damage went from \$500 to \$2,000.

\* In 2007, Total Hours Worked on the Recreational Boat Safety Program (RBS) was based on Federal Funded Boating Hours

\* In 2008, statistics were compiled to reflect the Federal Fiscal Year (10/01 – 09/30)

\* The total number of registered boats is based on calendar year

\* From 1997 - 2006 - Total Hours Worked on the Recreational Boat Safety Program (RBS) was based on Recreational Boating Enforcement Hours - 4131

## BOATING SAFETY EDUCATION

Illinois Department of Natural Resources (IDNR) boating safety courses are offered free to the public. The courses review boating laws and provide instruction on safe and attentive operation of watercraft. These courses are taught by dedicated, trained volunteers who are certified by the IDNR to teach safe boating classes. Many volunteers carry additional certification in boating safety instruction from the US Coast Guard Auxiliary or the US Power Squadrons. Course schedules are available by contacting the IDNR Safety Education Office at 800/832-2599, Ameritech Relay 800/526-0844, or TDD 217/782-9175. IDNR Safety Education provides course schedules and offers courses over the internet which can be accessed through the IDNR web site at <http://dnr.state.il.us>.

<b>Traditional Classroom Course</b>					<b>Boat-Ed Internet Course</b>				
<u>Year</u>	<u>Total Classes</u>	<u># of Students Certified</u>	<u># of Students Failed</u>	<u>Total Students</u>	<u>Year</u>	<u>Exams Issued</u>	<u>Certified</u>	<u>Failed</u>	<u>Success Rate</u>
<b>1993</b>	142	2,708	67	2,775	<b>2005*</b>	890	732	158	82%
<b>1994</b>	122	2,416	110	2,526	<b>2006</b>	1,693	1,405	288	83%
<b>1995</b>	125	2,863	81	2,944	<b>2007</b>	1,687	1,358	313	80%
<b>1996</b>	140	3,439	119	3,558	<b>2008</b>	1,699	1,362	313	80%
<b>1997</b>	133	3,147	91	3,238	<b>2009</b>	2,208	2,037	171	92%
<b>1998</b>	134	3,299	90	3,389	<b>Total</b>	<b>8,177</b>	<b>6,894</b>	<b>1,243</b>	<b>84%</b>
<b>1999</b>	137	3,920	85	4,005	<b>* In May 2005 the Boat-Ed internet course started</b>				
<b>2000</b>	147	4,196	80	4,276					
<b>2001</b>	144	3,315	65	3,380					
<b>2002</b>	152	3,765	64	3,829					
<b>2003</b>	145	3,772	68	3,840					
<b>2004</b>	111	2,699	61	2,760					
<b>2005*</b>	95	2,390	38	2,428					
<b>2006</b>	74	1,449	68	1,517					
<b>2007</b>	70	1,215	20	1,235					
<b>2008</b>	47	857	13	870					
<b>2009</b>	49	874	14	888					
<b>Total</b>	<b>1,967</b>	<b>46,324</b>	<b>1,134</b>	<b>47,458</b>					

Approximately 94% of all reported fatalities occurred on boats where the operator had not received, or it was unknown if the operator had received, boating safety instruction.

The Illinois Department of Natural Resources is concerned by the lack of boating safety education. Accident statistics demonstrate our current boating safety education requirement may not be reaching those age groups involved in the majority of accidents. The State of Illinois requires boating safety education for persons 12 to 17 years of age. Persons at least 18 years of age or older are not required to have boating safety education. The boating accident statistics show since 2000, 80% of injuries, 63% of fatalities, and 72% of watercraft involved in accidents were operated by persons between 20 and 59 years of age. The lack of boating safety education among operators between the ages of 20 and 59 is apparent in the accident statistics. In 2009, operators between the ages of 20 and 59 were involved in 76% of the boating accidents and 72% were involved in fatal boating accidents. Overall, 85% of watercraft involved in accidents were operated by persons whom had no formal boat safety education.

The Department of Natural Resources challenges all Conservation Police Officers and Volunteer Boat Safety Instructors to teach as many safety classes as possible, focusing on: PFDs, Inland Rules to Navigation, Boating Under the Influence, Reckless/Careless Operation, and the danger associated with Carbon Monoxide poisoning.

# REPORTING GUIDELINES FOR BOAT ACCIDENTS

A recreational boating accident means a recreational vessel, a numbered vessel, or a documented vessel is being used by its operator for recreational purposes and one or more of the following events occur involving the vessel or its equipment:

1. A person dies; or
2. A person disappears; or
3. A person has an injury that requires medical treatment greater than first aid; or
4. Damages resulting to the vessel(s) / property involved equal or exceed \$2,000; or
5. A total loss of vessel

## **AND**

The accident involved a recreational vessel, documented vessel being used for recreational purposes, OR a vessel that was required to be numbered BUT NOT required to be United States Coast Guard inspected.

## **AND**

The accident involved the vessel, or its associated equipment, in one of the following occurrences:

- Grounding;
- Capsizing;
- Flooding / Swamping;
- Falls within or overboard a vessel;
- Person(s) ejected from a vessel;
- Person leaves a vessel that is underway to swim for pleasure;
- Person leaves a vessel in an attempt to retrieve a lost item, another person, or another vessel;
- Sinking;
- Fire or Explosion;
- Skier Mishap;
- Collision with another vessel;
- Collision with object;
- The vessel, propeller, propulsion unit, or steering machinery strikes a person;
- Carbon Monoxide asphyxiation

As a general guideline, if any of the above events occur and there is a reasonable likelihood that as a result of the event(s) – an injury, death, or property damage occurs – the incident is a recreational boating accident.

Boat operators are required to report their accidents to authorities in the jurisdiction where the accident occurred. In cases involving personal injury, and/or property damage in excess of \$2,000, the operator must file a Boating Accident Report Form (BAR) with the IDNR within 5 days of the date of the accident. Accidents resulting in death must be reported to the IDNR on a BAR within 2 days of the accident.

# NON-REPORTABLE GUIDELINES

The following guidelines list occurrences directly or indirectly involving a vessel where vessel activities or operation DID NOT contribute to a boating accident. While these occurrences may be reported in the State of Illinois, they will be classified as “non-reportable recreational boating accidents.”

- a. A person dies or is injured from self-inflicted wounds, alcohol poisoning, ingestion of drugs, controlled substances or poison; or from gunshot wounds.
- b. A person dies or is injured from assault by another person or persons while aboard a vessel.
- c. A person dies or is injured from natural causes while aboard a vessel.
- d. A person dies or is injured while swimming for pleasure from a vessel that IS NOT underway (the vessel is anchored, moored, or docked). CAUTION needs to be exercised to confirm the vessel was used as a swimming platform only. The following are REPORTABLE boating accidents involving a swimmer, a recreational vessel and its operation:
  - A person dies or is injured while swimming because of Carbon Monoxide asphyxiation;
  - A person dies or is injured while swimming because a vessel is improperly connected to shore power and resultant stray electrical current enters the water causing electrocution;
  - A person dies or is injured after leaving a vessel that is underway to swim for pleasure because the vessel IS NOT anchored, moored, or docked and the swimmer is unable to get back to the vessel.
- e. A person dies or is injured in swimming to retrieve an object or a vessel that is adrift from its mooring or dock, having departed from the shore or pier.
- f. A person dies or is injured after falling or jumping from a swim raft that is moored or anchored for use as a swimming platform or other purpose.
- g. A person dies, is injured, or property damage occurs while preparing a vessel for launching or retrieving a vessel AND the vessel is not in or upon the water.
- h. Damage, injury, or death results from a fire on shore or a pier that spreads to a vessel or vessels.
- i. A person dies, is injured, or property damage results from an “ice boat” accident. An ice boat is a sail-powered device which rides on runners/blades over the ice on frozen lakes and rivers and carries at least the operator. It cannot be used as a conventional sailboat on open water.
- j. Damage, injury, or death on a docked or moored vessel resulting from storms or swell conditions
- k. Damage to a docked or moored vessel due to theft or any vandalism.
- l. Death, injury, or damage on a docked, moored, or anchored non-propelled houseboat or other vessel used primarily as a permanent residence.
- m. A person dies or is injured while using underwater breathing apparatus (i.e., snorkeling or scuba diving) and the vessel did not contribute to the casualty.

# REGISTERED RECREATIONAL BOATS

Illinois requires every watercraft, other than sailboards, on waters within the jurisdiction of this State to be numbered. No person may operate, or give permission for the operation of, any watercraft on such waters unless the watercraft is numbered in accordance with the Boat Registration & Safety Act, or in accordance with applicable Federal law, or in accordance with a Federally-approved numbering system of another State, and (1) the certificate of number awarded to such watercraft is in full force and effect, and (2) the identifying number set forth in the certificate of number is displayed on each side of the bow of such watercraft.

The owner of each watercraft requiring numbering by this State shall file an application for number with the Department of Natural Resources on forms approved by it. The application shall be signed by the owner of the watercraft and shall be accompanied by a fee as follows:

<b>Registration Fees</b>	<b>New &amp; Transfer</b>	<b>Renewal</b>	<b>Renewal</b>
Class A (all canoes, kayaks and paddleboats)	\$13.00		\$6.00
Class 1 (all watercraft less than 16 feet in length)	\$22.00		\$15.00
Class 2 (all watercraft 16 feet or more but less than 26 feet in length)	\$52.00		\$45.00
Class 3 (all watercraft 26 feet or more but less than 40 feet in length)	\$82.00		\$75.00
Class 4 (all watercraft 40 feet in length or more)	\$107.00		\$100.00

**Registration is valid for three years**

## 2009 REPORT OF CERTIFICATES OF NUMBER ISSUED TO BOATS RECREATIONAL BOATS ONLY\*

Hull Material	Total Mechanically Propelled					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	503	1,474	131	14	15	2,137
Fiberglass	25,853	46,328	43,885	1,651	865	118,582
Metal	1,061	147,539	1,548	14	13	150,175
Inflatable	26	1,949	15	1	0	1,991
Other	265	4,239	217	7	13	4,741
<b>Total</b>	<b>27,708</b>	<b>201,529</b>	<b>45,796</b>	<b>1,687</b>	<b>906</b>	<b>277,626</b>
Hull Material	Other Boats					
	Not Mechanically Propelled			Personal Watercraft	Other Boats	Total
	Rowboats	Sailboats	Canoes/ Kayaks			
Wood	166	214	718	24	71	1,193
Fiberglass	3,963	5,284	8,992	19,822	5,114	43,175
Metal	9,360	61	9,053	56	1,841	20,371
Inflatable	217	10	505	16	364	1,112
Other	1,755	354	25,007	313	2,624	30,053
<b>Total</b>	<b>15,461</b>	<b>5,923</b>	<b>44,275</b>	<b>20,231</b>	<b>10,014</b>	<b>95,904</b>
	<b>65,659</b>					


**Total Number of Registered Boats      329,255**

# 2009


## RECREATIONAL BOATS ONLY\* REPORT OF CERTIFICATES OF NUMBER ISSUED TO BOATS

Hull Material	Under 16 Feet					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	47	701	10	1	5	764
Fiberglass	8,597	12,793	706	7	61	22,164
Metal	196	55,021	97	0	2	55,316
Inflatable	25	1,913	10	0	0	1,948
Other	203	3,608	116	0	8	3,935
<b>Total</b>	<b>9,068</b>	<b>74,036</b>	<b>939</b>	<b>8</b>	<b>76</b>	<b>84,127</b>
Hull Material	16 to 26 Feet					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	377	755	105	0	8	1,245
Fiberglass	13,148	33,116	36,894	95	657	83,910
Metal	616	91,295	1,126	2	10	93,049
Inflatable	1	35	5	1	0	42
Other	47	622	93	1	3	766
<b>Total</b>	<b>14,189</b>	<b>125,823</b>	<b>38,223</b>	<b>99</b>	<b>678</b>	<b>179,012</b>
Hull Material	26 to 40 Feet					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	55	17	15	9	1	97
Fiberglass	3,122	397	6,098	1,358	142	11,117
Metal	154	1,166	198	6	1	1,525
Inflatable	0	0	0	0	0	0
Other	12	8	8	3	1	32
<b>Total</b>	<b>3,343</b>	<b>1,588</b>	<b>6,319</b>	<b>1,376</b>	<b>145</b>	<b>12,771</b>
Hull Material	40 to 65 Feet					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	23	1	1	3	1	29
Fiberglass	970	21	185	188	5	1,369
Metal	80	54	106	6	0	246
Inflatable	0	0	0	0	0	0
Other	3	1	0	3	1	8
<b>Total</b>	<b>1,076</b>	<b>77</b>	<b>292</b>	<b>200</b>	<b>7</b>	<b>1,652</b>
Hull Material	Over 65 Feet					
	Power			Auxiliary Sail		Total
	Inboard	Outboard	Sterndrive	Inboard	Outboard	
Wood	1	0	0	1	0	2
Fiberglass	16	1	2	3	0	22
Metal	15	3	21	0	0	39
Inflatable	0	1	0	0	0	1
Other	0	0	0	0	0	0
<b>Total</b>	<b>32</b>	<b>5</b>	<b>23</b>	<b>4</b>	<b>0</b>	<b>64</b>

Total Number of Registered Boats



Total Number of Registered Boats  
Not Mechanically Propelled



# BOATING STATISTICAL SUMMARY

Statistical information contained in this report is based on the Federal Fiscal Year 2009 (FFY09) (10/01/2008 – 09/30/2009), excluding the registered boats, which is based on calendar year 2009. Illinois had 102 USCG Reportable Accidents in FFY09, resulting in 71 injuries and 25 fatalities. On average, Illinois saw an overall safer year on the water, but did see an increase in fatal accidents. Last year Illinois had 120 USCG Reportable Accidents in FFY08, resulting in 78 injuries and 13 fatalities. The total number of registered boats continues to decline from 336,025 last year to 329,032 this year. This equates to 21.6 injuries and 7.6 fatalities per 100,000 registered boats. The ten year Illinois average is 109 accidents, 72 injuries and 16 fatalities.

In FFY09, the Illinois Department of Natural Resources Office of Law Enforcement saw a significant decrease in the amount of hours worked on the Recreational Boat Safety Program (RBS) from FFY08. A total of 21,403 hours were spent on the program, which was a 46.5% decrease from the previous year's total of 39,998. There were several factors believed to have caused the decrease in hours worked and the increase in enforcement activity.

In contrast to the decrease of man hours worked, enforcement activity increased significantly overall. During the 2009 recreational boating season, Conservation Police Officers (CPOs) made 179 operating under the influence (OUI) of alcohol or drugs arrests. Other Law Enforcement agencies made 36 OUI arrests, for a total of 215 OUI arrests. CPO emphasis on OUI enforcement remains a high priority. All officers have been trained in OUI detection and arrest procedures. In addition to an increase of OUI arrests, there were 1,960 citations issued and 5,576 written warnings in FFY09, compared to 1,603 citations and 3,695 written warnings the previous year for various infractions of the Boat Registration & Safety Act. CPOs inspected 17,762 vessels, provided assistance to a combination of 1,219 persons and vessels, and conducted 99 search and rescue missions. CPOs also conducted enforcement details throughout the State. The details focused on alcohol, PFD, and reckless/careless operation violations. Boating enforcement is considered to be a high priority and maximum available coverage was provided.

Boating accident reports indicate the majority of accidents occur between June and August, on Saturday or Sunday, between 12 p.m. and 6 p.m. Conditions are usually clear with good visibility, light winds, and calm water. Most accidents involve operators between the ages of twenty and forty who have over one hundred hours of boating experience but have little or no classroom boating safety instruction. They also involve open motorboats cruising in a careless/reckless manner culminating in a collision with another boat.

Twenty-five people died in Illinois boating accidents in 2009. In this reporting period, most fatalities occurred during the week between 6 p.m. and 12 a.m. with clear conditions and calm waters. The winds were calm to light with good visibility. Open motorboats less than 20 feet in length were involved in 16 fatalities. In the majority of fatalities, the operators had no formal boat safety education.

Five fatalities were caused by Carbon Monoxide (CO) Poisoning. The contributing factors were equipment failure and lack of carbon monoxide detector on board the vessel. In an attempt to reduce the number of CO fatalities, an informational campaign was conducted by the Conservation Police. The campaign focuses on educating the recreational boating public, marinas, boat dealers, and repair shops on the dangers of CO poisoning.

Once again, the factor that would have saved lives this past season would have been for people to wear their Personal Floatation Devices (PFD). Of 25 fatalities, 12 may have survived if they had worn their PFDs. Six people died from blunt force trauma and other injuries. The leading type of accidents involving fatalities were collisions with falls overboard and flooding / swamping.

The State of Illinois does not require a Coast Guard-approved PFD to be worn. However, persons under the age of 13, and operators/passengers on personal watercraft or specialty prop-craft, are required to wear a Coast Guard-approved PFD. The most proactive action a boater can do to ensure his/her safety on the water is wearing a Coast Guard-approved PFD of the appropriate size and in serviceable condition.

# BOATING ENFORCEMENT – Federal Fiscal Year 2009

Illinois' Boating Enforcement was compiled to reflect the Federal Fiscal Year (10/01/2008 – 09/30/2009).

## Top Boating Violations

<b>Top Citations</b>		
	<b>Type of Boating Violations</b>	<b># of Citations</b>
1	PFD Wearable Type I, II, or III Required	595
2	Operating While Under The Influence Of Alcohol Or Drugs	213
3	Operation Of Unnumbered Watercraft	176
4	PFD-Age Requirement. Less Than 13 Years Old Must Wear PFD	148
5	Operating While Under The Influence Of Alcohol W/BAC Over .08	121
6	Operation In a No Wake Area	104
7	Operation Of a Motorboat W/Out Fire Extinguisher In Serviceable Condition	95
8	Failure To Display Valid Registration Expiration Decal	50
9	Waterskiing-Competent Observer; Vessel Capacity-3 Persons	49
10	Operation In Restricted Area; W/In 150 Ft Of Public Ramp	44
11	Lights-Operation Of Watercraft W/Out Proper Lights-Sunset/Sunrise	39
12	Failure To Transfer Certificate Of Number	38
13	PFD Type IV PFD On Board Vessel 16 Feet And Longer	38
14	Passenger Location-No Riding On Gunwales, Seatbacks	33
15	Careless Operation Of A Watercraft	28
	<b>Total Number of Citations Issued</b>	<b>1960</b>

## Top Written Warnings

	<b>Type of Boating Violations</b>	<b># of Written Warnings</b>
1	Battery Covers	1103
2	PFD Wearable Type I, II, or III Required	864
3	Operation Of a Motorboat W/Out Fire Extinguisher In Serviceable Condition	710
4	Operation Of Watercraft W/Out Horn Or Whistle	674
5	Operation Of Unnumbered Watercraft	638
6	PFD Type IV PFD On Board Vessel 16 Feet And Longer	295
7	Operation In a No Wake Area	207
8	Passenger Location-No Riding On Gunwales, Seatbacks	194
9	Lights-Operation Of Watercraft W/Out Proper Lights-Sunset/Sunrise	148
10	Failure To Display, Improper Display Of Valid Registration Number	121
11	Lanyard Cut-Off Switch	101
12	PFD-Age Requirement. Less Than 13 Years Old Must Wear PFD	83
13	Failure To Display Valid Registration Expiration Decal	81
14	Visual Distress Signals (Lake Michigan/Vessels 16 Ft Or Greater)	71
15	Failure To Transfer Certificate Of Number	59
	<b>Total Number of Written Warnings Issued</b>	<b>5567</b>

## Boat Registration Inspections

Year	Type of Boat Inspections	Region I	Region II	Region III	Region IV	Region V	Total
2009	Boat Registration Inspections	172	177	82	101	45	577
	Junk Boat Reports	4	1	0	0	0	5
<b>Total</b>		<b>176</b>	<b>178</b>	<b>82</b>	<b>101</b>	<b>45</b>	<b>582</b>

Boat Registration Inspections are conducted when the owner attempts to register a vessel and the title, registration, or hull identification number is missing or in question. Officers will physically inspect the vessel to confirm information and conduct investigations into the transfer of titles. The officer will then complete an inspection either approving or denying the title/registration of the vessel. This is the first full year the program has been implemented and the Boat Registration Division has already seen a drastic reduction in fraudulent applications. Several vessels have also been identified as stolen and recovered that would have been registered without the program in place.

Junk Boat Reports are conducted when the vessel is going to be destroyed.

## Operating Under the Influence (OUI) Arrests

Year	Region I	Region II	Region III	Region IV	Region V	Lake Michigan	Other Agency	Total
1993	18	10	11	10	3	5	69	126
1994	20	7	2	21	5	12	22	89
1995	48	11	5	27	7	13	11	122
1996	29	28	4	22	6	4	37	130
1997	41	41	5	20	7	9	35	158
1998	36	13	11	7	7	1	37	112
1999	49	6	9	18	11	3	63	159
2000	33	10	16	21	18	3	73	174
2001	73	27	15	28	34	4	60	241
2002	84	27	25	23	36	5	75	275
2003	55	13	6	19	25	7	63	188
2004	39	31	19	21	17	0	62	189
2005	49	34	17	54	31	0	93	278
2006	58	76	23	41	31	0	73	302
2007	36	34	23	30	21	0	46	190
2008	48	32	29	22	23	0	31	185
2009	58	42	18	30	31	0	36	215
<b>Total</b>	<b>774</b>	<b>442</b>	<b>238</b>	<b>414</b>	<b>313</b>	<b>66</b>	<b>886</b>	<b>3133</b>

\* In 2004, Lake Michigan was absorbed into Region II.

## Boating Accidents and Alcohol Use

	<b>OUI Arrests</b>	<b>Accidents</b>			<b>Injuries</b>			<b>Fatalities</b>			<b>Vessels</b>		
<b>Year</b>	<b>Total Number of OUI</b>	<b>Primary Cause Alcohol Use</b>	<b>Total Number of Accidents</b>	<b>Percentage Involving Alcohol Use</b>	<b>Primary Cause Alcohol Use</b>	<b>Total Number of Injuries</b>	<b>Percentage Involving Alcohol use</b>	<b>Primary Cause Alcohol Use</b>	<b>Total Number of Fatalities</b>	<b>Percentage involving Alcohol Use</b>	<b>Primary Cause Alcohol Use</b>	<b>Total Number of Vessels</b>	<b>Percentage Involving Alcohol Use</b>
1993	126	0	0	0	0	0	0	0	0	0	25	265	9.43%
1994	89	0	0	0	0	0	0	0	0	0	12	290	4.14%
1995	122	0	0	0	0	0	0	0	0	0	15	303	4.95%
1996	130	0	0	0	0	0	0	0	0	0	17	151	11.26%
1997	158	0	0	0	0	0	0	0	0	0	0	0	0
1998	112	0	0	0	0	0	0	0	0	0	23	239	9.62%
1999	159	0	0	0	0	0	0	0	0	0	0	0	0
2000	174	5	153	3.27%	7	76	9.21%	1	14	7.14%	7	231	3.03%
2001	241	8	112	7.14%	10	75	13.33%	2	23	8.70%	11	171	6.43%
2002	275	6	135	4.44%	5	92	5.43%	3	8	37.50%	8	188	4.26%
2003	188	8	84	9.52%	9	63	14.29%	5	13	38.46%	12	122	9.84%
2004	189	5	78	6.41%	2	45	4.44%	5	18	27.78%	7	103	6.80%
2005	278	8	115	6.96%	8	100	8.00%	2	16	12.50%	12	152	7.89%
2006	302	9	79	11.39%	11	66	16.67%	5	18	27.78%	13	119	10.92%
2007	190	7	107	6.54%	3	57	5.26%	1	13	7.69%	7	146	4.79%
2008	185	5	120	4.17%	1	78	1.28%	1	13	7.69%	4	174	2.30%
2009	215	11	102	10.78%	9	71	12.68%	2	25	8.00%	12	137	8.76%
<b>Total</b>	<b>3133</b>	<b>72</b>	<b>1085</b>	<b>6.64%</b>	<b>65</b>	<b>723</b>	<b>8.99%</b>	<b>27</b>	<b>161</b>	<b>16.77%</b>	<b>185</b>	<b>2791</b>	<b>6.63%</b>



# BOATING ACCIDENT REPORT – Federal Fiscal Year 2009

Statistical information contained in this report is based on the Federal Fiscal Year 2009 (FFY09) (10/01/2008 – 09/30/2009), excluding the registered boats, which is based on calendar year 2009.

<b>Total Number of Accidents</b>	<b>Total Number of Injuries</b>	<b>Total Number of Fatalities</b>	<b>Total Number of Vessels</b>	<b>Total Number of Registered Boats</b>
102	71	25	137	329,032

<b>Number of Accidents per 100,000 Registered Boats</b>	<b>Number of Injuries per 100,000 Registered Boats</b>	<b>Number of Fatalities per 100,000 Registered Boats</b>
31.0	21.6	7.6

**CAUSE OF DEATH**

Drowning	14
Trauma	1
Carbon Monoxide Poisoning	5
Sudden Medical Condition	2
Unknown	3
<b>Total</b>	<b>25</b>

**VICTIM ACTIVITY**

Fishing	9
Making Repair	1
None	3
Paddle Boating	2
Preparing for Bed	4
Swimming	1
White Water Sports	1
Unknown	1
<b>Total</b>	<b>25</b>

**USE OF PFD**

Not Worn	20
Worn	3
Unknown	2
<b>Total</b>	<b>25</b>

**PRIMARY TYPE OF INJURY**

Amputation	2
Back Injury	2
Broken Bones	14
Burns	3
Carbon Monoxide Exposure	1
Contusion	15
Dislocation	2
Head Injury	6
Hypothermia	8
Internal Injuries	5
Laceration	8
Neck Injury	2
Shock	1
Sprain/Strain	1
Unknown	1
<b>Total</b>	<b>71</b>

**INJURY CAUSE**

Carbon Monoxide	1
Explosion	1
Explosion of Fuel Vapors	2
Exposure to Elements	10
Finger in Engine Vent	1
Fire	2
Impact With Boat	27
Impact With Fixed/Floating Object	10
Impact With Water	9
Jet Propulsion Wash	1
Struck By Propeller	7
<b>Total</b>	<b>71</b>

**ACCIDENT STATISTICS BY  
DAY OF THE WEEK**

<u>Day of Week</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Sunday	29	14	10	41
Monday	6	4	0	10
Tuesday	4	5	1	6
Wednesday	5	0	4	5
Thursday	10	9	4	11
Friday	6	4	3	9
Saturday	42	35	3	55
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
MONTH OF THE YEAR**

<u>Month</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
January	0	0	0	0
February	1	1	1	1
March	1	0	1	1
April	5	2	2	5
May	10	5	0	14
June	28	27	5	39
July	21	11	3	31
August	17	15	2	23
September	8	3	1	11
October	6	4	6	6
November	2	0	4	3
December	3	3	0	3
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
TIME OF DAY**

<u>Time</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Unknown	0	0	0	0
12:01 a.m. - 6:00 a.m.	6	4	4	8
6:01 a.m. - 12:00 noon	13	7	3	16
12:01 p.m. - 6:00 p.m.	54	40	8	75
6:01 p.m. - 12:00 a.m.	29	20	10	38
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY WATER CONDITIONS

<u>Water</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Calm (Waves < 6")	56	39	16	77
Choppy (Waves 6"-2')	34	26	4	46
Rough (Waves 2'-6')	6	2	3	7
Very Rough (Waves >6')	1	0	0	1
Strong /Swift Current	3	3	2	3
Unknown	2	1	0	3
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY WEATHER CONDITIONS

<u>Weather</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Clear	79	49	21	109
Cloudy	15	14	1	18
Fog	1	0	0	1
Rain	6	8	3	8
Hazy	0	0	0	0
Unknown	1	0	0	1
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY WIND CONDITIONS

<u>Wind</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
None	6	6	1	7
Light (0-6 mph)	70	52	13	95
Moderate (7-14 mph)	16	10	4	22
Strong(15-25 mph)	2	0	1	3
Stormy ( >25 mph)	0	0	0	0
Unknown	8	3	6	10
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY VISIBILITY

<u>Visibility</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Good	92	65	20	123
Fair	5	6	2	6
Poor	3	0	3	5
Unknown	2	0	0	3
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY PRIMARY CAUSE OF ACCIDENT

<u>Primary Cause</u>	<u>#Accidents</u>	<u># Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Alcohol Use	11	9	2	12
Careless/Reckless Operation	10	4	0	10
Congested Waters	3	3	1	4
Dam/Lock	0	0	0	0
Equipment Failure	7	0	0	7
Excessive Speed	3	2	0	3
Failure to Vent	1	1	0	1
Force of Wake	6	9	0	6
Hazardous Waters	6	8	0	6
Hull Failure	0	0	0	0
Ignition of Spilled Fuel or Vapors	3	4	0	3
Improper Loading	2	0	0	1
Machinery Failure	5	2	6	5
Medical Condition	2	0	2	2
No Proper Lookout	2	0	0	2
Operator Inattention	11	2	0	14
Operator Inexperience	4	4	3	8
Other Vessel Fault	0	9	0	22
Overloading	0	0	1	1
Passenger/Skier Behavior	3	2	1	3
Sharp Turn	3	2	0	2
Standing/Sitting in Inappropriate Position	4	4	2	5
Weather (Heavy)	5	0	1	6
Other	4	5	1	7
Unknown	7	1	5	7
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
TYPE OF ACCIDENT**

<b><u>Type Of Accident</u></b>	<b><u># Injuries</u></b>	<b><u># Fatalities</u></b>	<b><u>#Vessels</u></b>
Capsizing	6	2	5
Carbon Monoxide Exposure	1	5	2
Collision w/vessel	21	0	58
Collision w/fixed object	7	0	9
Collision w/floating object	0	0	0
Fall on a Vessel	1	0	1
Fall in boat	0	1	2
Falls overboard	4	7	10
Fire/Explosion (fuel)	3	0	2
Fire/Explosion (Other than fuel)	0	0	3
Flooding/Swamping	7	4	10
Grounding	0	1	2
Person Departed Vessel	2	4	6
Person Ejected from a Vessel	11	0	10
Sinking	0	0	1
Skier Mishap	1	0	1
Starting Engine	2	1	4
Struck by boat	0	0	2
Struck by Motor / Propeller	2	0	2
Struck submerged object	1	0	2
Unknown	1	0	4
Other	1	0	1
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
VESSEL LENGTH IN FEET**

<b><u>Vessel Length in Feet</u></b>	<b><u>#Injuries</u></b>	<b><u>#Fatalities</u></b>	<b><u>#Vessels</u></b>
Less than 10 feet	16	0	14
10 feet to less than 16 feet	22	8	34
16 feet to less than 20 feet	5	8	21
20 feet to less than 26 feet	19	4	41
26 feet to less than 40 feet	5	5	18
Over 40 feet	0	0	5
Unknown	4	0	4
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
TYPE OF BOAT**

<b><u>Type Of Boat</u></b>	<b><u>#Injuries</u></b>	<b><u>#Fatalities</u></b>	<b><u>#Vessels</u></b>
Auxiliary Sail	2	0	3
Cabin Motorboat	5	2	22
Canoe	2	2	3
Houseboat	0	4	1
Inflatable	6	1	2
Jet Boat	2	0	5
Kayak	2	0	2
Open Motorboat	20	12	52
Paddle Boat	1	3	3
Personal Watercraft	23	0	30
Pontoon	7	0	10
Sail Only	0	1	1
Other	0	0	1
Unknown	1	0	2
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
OPERATION AT TIME OF ACCIDENT**

<b><u>Vessel Operation</u></b>	<b><u>#Injuries</u></b>	<b><u>#Fatalities</u></b>	<b><u>#Vessels</u></b>
At Anchor	4	7	9
Changing Direction	9	0	10
Changing Speed	5	1	15
Cruising	29	3	51
Docking/Undocking	0	0	6
Drifting	11	5	22
Launching	2	0	2
Rowing/Padding	8	6	7
Sailing	0	1	1
Tied to Dock/mooring	2	0	8
Unknown	1	1	3
Other	0	1	3
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY OPERATOR EDUCATION

<u>Operator Education</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
American Red Cross	0	0	0
Informal	5	4	11
State Course	9	1	14
U.S. Power Squadron	2	0	4
U.S.C.G. Auxiliary	2	0	3
None	38	7	64
Unknown	15	13	41
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY OPERATOR EXPERIENCE

<u>Operator Experience</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Under 10 hours	15	5	17
10 - 100 hours	20	3	34
Over 100 hours	27	9	62
Unknown	9	8	24
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

## ACCIDENT STATISTICS BY OPERATOR AGE

<u>Operator Age</u>	<u>#Injuries</u>	<u>Fatalities</u>	<u>#Vessels</u>
< 10	0	0	0
10-12	0	0	0
13-17	5	1	10
18-19	2	2	3
20-29	19	1	19
30-39	18	5	36
40-49	15	8	33
50-59	9	4	16
60-69	1	4	11
70 +	2	0	5
Unknown	0	0	4
<b>Total</b>	<b>71</b>	<b>25</b>	<b>137</b>

**ACCIDENT STATISTICS BY  
BODY OF WATER**

<b><u>Body Of Water</u></b>	<b><u>#Accidents</u></b>	<b><u>#Injuries</u></b>	<b><u>#Fatalities</u></b>	<b><u>#Vessels</u></b>
Benton City Lake	1	0	0	1
Calumet River	3	1	2	3
Carlyle Lake	3	2	0	5
Clinton Lake	2	1	0	3
Cook County Forest Preserve Pond	1	0	1	1
Crystal Lake	1	1	0	2
Fox Lake	1	0	1	1
Fox River	7	6	3	9
Gillespie Lake	1	0	0	2
Grass Lake	4	5	0	4
Holiday Shores	1	1	0	2
Illinois River	17	15	2	25
Kankakee River	4	7	0	7
Kaskaskia River	1	1	0	1
Kickapoo Creek	1	1	0	1
Lake Carroll	1	0	0	2
Lake Lou Yaeger	2	0	2	2
Lake Marie	1	1	0	1
Lake Michigan	7	2	0	11
Lake Sangchris	1	0	1	1
Lake Shannon	1	1	0	2
Lake Shelbyville	3	3	1	3
Lake Springfield	2	0	0	3
Lake Taylorville	1	0	0	1
Lake Vermilion	1	1	0	1
Mill Creek Lake	2	1	0	3
Mississippi River	12	6	5	13
Nippersink Lake	2	2	0	4
Petite Lake	4	3	0	7
Powerton Lake	1	0	0	1
Rend Lake	2	1	1	2
Rice Lake FWA	1	0	1	1
Rock River	4	2	1	6
Sam Dale State Park Lake	1	0	1	1
Senachwine Lake	1	0	1	1
Vermilion River	3	6	2	3
Wonder Lake	1	1	0	1
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

**BODY OF WATER BROKEN DOWN  
BY COUNTY**

<u>Waterway</u>		<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Benton City Lake	Franklin County	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
Calumet River	Cook County	3	1	2	3
	<b>Subtotal</b>	<b>3</b>	<b>1</b>	<b>2</b>	<b>3</b>
Carlyle Lake	Clinton County	3	2	0	5
	<b>Subtotal</b>	<b>3</b>	<b>2</b>	<b>0</b>	<b>5</b>
Clinton Lake	Dewitt County	2	1	0	3
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>3</b>
Cook County Forest Preserve Pond	Cook County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Crystal Lake	McHenry County	1	1	0	2
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>2</b>
Fox Lake	Lake County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Fox River	Kane County	2	1	0	2
	McHenry County	5	5	3	7
	<b>Subtotal</b>	<b>7</b>	<b>6</b>	<b>3</b>	<b>9</b>
Gillespie Lake	Macoupin County	1	0	0	2
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>2</b>
Grass Lake	Lake County	4	5	0	4
	<b>Subtotal</b>	<b>4</b>	<b>5</b>	<b>0</b>	<b>4</b>

## Body of Water Broken Down By County cont.

Waterway		#Accidents	#Injuries	#Fatalities	#Vessels
Holiday Shores					
	Madison County	1	1	0	2
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>2</b>
Illinois River					
	Grundy County	1	1	0	1
	Jersey County	2	4	0	3
	LaSalle County	8	7	1	11
	Peoria County	2	2	0	4
	Tazewell County	3	1	1	5
	Woodford County	1	0	0	1
	<b>Subtotal</b>	<b>17</b>	<b>15</b>	<b>2</b>	<b>25</b>
Kankakee River					
	Kankakee County	4	7	0	7
	<b>Subtotal</b>	<b>4</b>	<b>7</b>	<b>0</b>	<b>7</b>
Kaskaskia River					
	St. Clair County	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Kickapoo Creek					
	Peoria County	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Lake Carroll					
	Carroll County	1	0	0	2
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>2</b>
Lake Lou Yeager					
	Montgomery County	2	0	2	2
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>2</b>
Lake Marie					
	Lake County	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Lake Michigan					
	Cook County	3	2	0	4
	Lake County	4	0	0	7
	<b>Subtotal</b>	<b>7</b>	<b>2</b>	<b>0</b>	<b>11</b>
Lake Sangchris					
	Christian County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>

**Body of Water Broken Down By County cont.**

<b>Waterway</b>		<b>#Accidents</b>	<b>#Injuries</b>	<b>#Fatalities</b>	<b>#Vessels</b>
Lake Shannon	Kankakee County	1	1	0	2
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>2</b>
Lake Shelbyville	Moultrie County	2	1	1	2
	Shelby County	1	2	0	1
	<b>Subtotal</b>	<b>3</b>	<b>3</b>	<b>1</b>	<b>3</b>
Lake Springfield	Sangamon County	2	0	0	3
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>0</b>	<b>3</b>
Lake Taylorville	Christian County	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
Lake Vermilion	Vermilion County	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Mill Creek Lake	Clark County	2	1	0	3
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>3</b>
Mississippi River	Adams County	1	0	0	1
	Calhoun County	3	0	4	3
	Carroll County	1	1	0	1
	Hancock County	1	0	0	1
	Henderson County	1	1	0	1
	Jersey County	2	2	0	2
	Monroe County	1	0	1	1
	Rock Island County	2	2	0	3
	<b>Subtotal</b>	<b>12</b>	<b>6</b>	<b>5</b>	<b>13</b>
Nippersink Lake	Lake County	2	2	0	4
	<b>Subtotal</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>4</b>
Petite Lake	Lake County	4	3	0	7
	<b>Subtotal</b>	<b>4</b>	<b>3</b>	<b>0</b>	<b>7</b>

**Body of Water Broken Down By County cont.**

<b>Waterway</b>		<b>#Accidents</b>	<b>#Injuries</b>	<b>#Fatalities</b>	<b>#Vessels</b>
Powerton Lake	Tazewell County	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
Rend Lake	Franklin County	1	0	1	1
	Jefferson County	1	1	0	1
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>2</b>
Rice Lake FWA	Fulton County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Rock River	Rock Island County	1	1	1	1
	Winnebago County	3	1	0	5
	<b>Subtotal</b>	<b>4</b>	<b>2</b>	<b>1</b>	<b>6</b>
Sam Dale State Park Lake	Wayne County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Senachwine Lake	Putnam County	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Vermilion River	LaSalle County	3	6	2	3
	<b>Subtotal</b>	<b>3</b>	<b>6</b>	<b>2</b>	<b>3</b>
Wonder Lake	McHenry County	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
<b>Total</b>		<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>



## ACCIDENT STATISTICS BY COUNTY

<u>County</u>	<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Adams County	1	0	0	1
Calhoun County	3	0	4	3
Carroll County	2	1	0	3
Christian County	2	0	1	2
Clark County	2	1	0	3
Clinton County	3	2	0	5
Cook County	7	3	3	8
DeWitt County	2	1	0	3
Franklin County	2	0	1	2
Fulton County	1	0	1	1
Grundy County	1	1	0	1
Hancock County	1	0	0	1
Henderson County	1	1	0	1
Jefferson County	1	1	0	1
Jersey County	4	6	0	5
Kane County	2	1	0	2
Kankakee County	5	8	0	9
Lake County	16	11	1	24
LaSalle County	11	13	3	14
Macoupin County	1	0	0	2
Madison County	1	1	0	2
McHenry County	7	7	3	10
Monroe County	1	0	1	1
Montgomery County	2	0	2	2
Moultrie County	2	1	1	2
Peoria County	3	3	0	5
Putnam County	1	0	1	1
Rock Island County	3	3	1	4
Sangamon County	2	0	0	3
Shelby County	1	2	0	1
St. Clair County	1	1	0	1
Tazewell County	4	1	1	6
Vermilion County	1	1	0	1
Wayne County	1	0	1	1
Winnebago County	3	1	0	5
Woodford County	1	0	0	1
<b>Total</b>	<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>

**COUNTIES BROKEN DOWN BY  
BODY OF WATER**

<u>County</u>		<u>#Accidents</u>	<u>#Injuries</u>	<u>#Fatalities</u>	<u>#Vessels</u>
Adams County	Mississippi River	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
Calhoun County	Mississippi River	3	0	4	3
	<b>Subtotal</b>	<b>3</b>	<b>0</b>	<b>4</b>	<b>3</b>
Carroll County	Lake Carroll	1	0	0	2
	Mississippi River	1	1	0	1
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>3</b>
Christian County	Lake Sangchris	1	0	1	1
	Lake Taylorville	1	0	0	1
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>1</b>	<b>2</b>
Clark County	Mill Creek Lake	2	1	0	3
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>3</b>
Clinton County	Carlyle Lake	3	2	0	5
	<b>Subtotal</b>	<b>3</b>	<b>2</b>	<b>0</b>	<b>5</b>
Cook County	Calumet River	3	1	2	3
	Cook County Forest Preserve Pond	1	0	1	1
	Lake Michigan	3	2	0	4
	<b>Subtotal</b>	<b>7</b>	<b>3</b>	<b>3</b>	<b>8</b>
Dewitt County	Clinton Lake	2	1	0	3
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>3</b>
Franklin County	Benton City Lake	1	0	0	1
	Rend Lake	1	0	1	1
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>1</b>	<b>2</b>
Fulton County	Rice Lake FWA	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Grundy County	Illinois River	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>

### Counties Broken Down By Body of Water cont.

County		#Accidents	#Injuries	#Fatalities	#Vessels
Hancock County	Mississippi River	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
Henderson County	Mississippi River	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Jefferson County	Rend Lake	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Jersey County	Illinois River	2	4	0	3
	Mississippi River	2	2	0	2
	<b>Subtotal</b>	<b>4</b>	<b>6</b>	<b>0</b>	<b>5</b>
Kane County	Fox River	2	1	0	2
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>0</b>	<b>2</b>
Kankakee County	Kankakee River	4	7	0	7
	Lake Shannon	1	1	0	2
	<b>Subtotal</b>	<b>5</b>	<b>8</b>	<b>0</b>	<b>9</b>
Lake County	Fox Lake	1	0	1	1
	Grass Lake	4	5	0	4
	Lake Marie	1	1	0	1
	Lake Michigan	4	0	0	7
	Nippersink Lake	2	2	0	4
	Petite Lake	4	3	0	7
	<b>Subtotal</b>	<b>16</b>	<b>11</b>	<b>1</b>	<b>24</b>
LaSalle County	Illinois River	8	7	1	11
	Vermillion River	3	6	2	3
	<b>Subtotal</b>	<b>11</b>	<b>13</b>	<b>3</b>	<b>14</b>
Macoupin County	Gillespie Lake	1	0	0	2
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>2</b>

### Counties Broken Down By Body of Water cont.

County		#Accidents	#Injuries	#Fatalities	#Vessels
Madison County					
	Holiday Shores Lake	1	1	0	2
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>2</b>
McHenry County					
	Crystal Lake	1	1	0	2
	Fox River	5	5	3	7
	Wonder Lake	1	1	0	1
	<b>Subtotal</b>	<b>7</b>	<b>7</b>	<b>3</b>	<b>10</b>
Monroe County					
	Mississippi River	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Montgomery County					
	Lake Lou Yeager	2	0	2	2
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>2</b>
Moultrie County					
	Lake Shelbyville	2	1	1	2
	<b>Subtotal</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>2</b>
Peoria County					
	Illinois River	2	2	0	4
	Kickapoo Creek	1	1	0	1
	<b>Subtotal</b>	<b>3</b>	<b>3</b>	<b>0</b>	<b>5</b>
Putnam County					
	Senachwine Lake	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Rock Island County					
	Mississippi River	2	2	0	3
	Rock River	1	1	1	1
	<b>Subtotal</b>	<b>3</b>	<b>3</b>	<b>1</b>	<b>4</b>
Sangamon County					
	Lake Springfield	2	0	0	3
	<b>Subtotal</b>	<b>2</b>	<b>0</b>	<b>0</b>	<b>3</b>
Shelby County					
	Lake Shelbyville	1	2	0	1
	<b>Subtotal</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>1</b>
St Clair County					
	Kaskaskia River	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>

**Counties Broken Down By Body of Water cont.**

<b>County</b>		<b>#Accidents</b>	<b>#Injuries</b>	<b>#Fatalities</b>	<b>#Vessels</b>
Tazewell County					
	Illinois River	3	1	1	5
	Powerton Lake	1	0	0	1
	<b>Subtotal</b>	<b>4</b>	<b>1</b>	<b>1</b>	<b>6</b>
Vermilion County					
	Vermilion Lake	1	1	0	1
	<b>Subtotal</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>1</b>
Wayne County					
	Sam Dale State Park Lake	1	0	1	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>1</b>
Winnebago County					
	Rock River	3	1	0	5
	<b>Subtotal</b>	<b>3</b>	<b>1</b>	<b>0</b>	<b>5</b>
Woodford					
	Illinois River	1	0	0	1
	<b>Subtotal</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>
<b>Total</b>		<b>102</b>	<b>71</b>	<b>25</b>	<b>137</b>



# Fatal Boat Accident Narratives



2009

# 2009 Fatal Boat Accident Narratives

1. On October 5<sup>th</sup>, 2008, four subjects were spending the night on Mississippi River. While onboard a vessel, the four subjects succumbed to carbon monoxide (CO) poisoning. There were several factors that contributed in the fatalities. First factor was the operation of an onboard generator located in the hull of the vessel. Secondly, the vessel had an open hull design, which allowed CO to travel through the entire vessel. Closed doors and windows in conjunction with utilizing the electric furnace facilitated the distribution of CO. The generator was needed to operate the furnace. Finally, there were no batteries in the Smoke/CO detector.

Contributing Factors: Machinery Failure

Failure to Vent

No Batteries in carbon monoxide detector on board the vessel

2. Conservation Police became aware of this accident after receiving a Coroner's Report of Death Resulting from Boating Accident Form in February 2009. The report indicated that the victim's cause of death was complications of a sub-dural hematoma and spinal cord injury with paralysis due to the boating accident in October 2008. The operator of the vessel, the victim's grandson, said he was not aware of the requirement to report the accident to authorities. A Conservation Police Officer met with the victim's family and the accident was described as follows: The victim's boat passed a barge on the left and was in the choppy wake caused by the barge. Two other boats then passed the victim's boat and another ski boat approached from the head on the right side. The victim's boat hit a large wake. The victim was sitting on the left side of the boat and had been bending over to pick up her cup of water when the boat hit another large wake. The victim began slumping down. She was transported from the marina to the hospital. The family does not believe her death was caused from the accident. They believe the hospital and the nursing home where the victim ended up at were responsible for the death. The victim was released from the hospital initially in a back brace and the family was told that the head injury was no longer a concern. The victim subsequently suffered paralysis in her legs, was re-admitted to the hospital, and then admitted to a nursing home where she developed a bed sore and became septic.

Contributing Factors: Congested Waters

Force of Wake

3. On October 26<sup>th</sup>, 2008, two subjects were spending the night on Lake Shelbyville. The victim died as a result of carbon monoxide poisoning. In addition, a second subject was treated for carbon monoxide poisoning after an onboard generator exhaust manifold gasket failed on their cabin motorboat. An investigation determined an improperly maintained generator in conjunction with the use of a severely kinked auto exhaust hose caused lethal amounts of carbon monoxide to contaminate the interior of the vessel.

Contributing Factors: Machinery Failure

Failure to Vent

Position of victim's body in relation to carbon monoxide source

Lack of carbon monoxide detector on board the vessel

4. On November 9<sup>th</sup>, 2008, the victim was testing a new motor and overrode the kill switch on the Illinois River. The victim reportedly launched his boat the day before. A police officer observed a truck and trailer in the parking lot. The officer located the victim's house and spoke with his father. The boat was discovered unattended the same day. The boat was a few feet from the shoreline. The motor was down in the mud, in gear, and not running. The depth finder was on. The victim was either ejected from the vessel or fell overboard. An extensive land, water, and air search was conducted. Unfortunately, the search efforts were unsuccessful in locating the victim. Several months later, the victim's body was located by three goose hunters. The coroner stated the preliminary findings indicated drowning as the cause of death.

Contributing Factors: Unknown

Failure to Wear Personal Floatation Device (PFD)

5. On November 14<sup>th</sup>, 2008, three subjects snuck out of their dorm to utilize paddle boats on the Fox River. Vessel 1 began to take on water and sink because the drain plug was not in it. The operator of vessel 1 jumped into the water. Vessel 2 occupants entered the river in their paddle boat to assist those on vessel 1. Both occupants of vessel 2 jumped into the river to help the operator of vessel 1. However, their attempts to assist him failed. All three individuals drowned and were recovered later in the day. No enforcement action was taken.

Contributing Factors: Operator Inexperience

Hazardous Waters

Weather

Failure to Wear Personal Floatation Device (PFD)

6. On February 26<sup>th</sup>, 2009, three subjects set out in the afternoon to do some fishing and drink some beer on the Rock River. About ten minutes into their trip, the owner of the canoe started to fish while the other two paddled. As they took turns paddling and fishing, the subject in the front was attempting to get a cigarette out and dropped them from his pocket. As he dropped them, he attempted to catch them causing the canoe to become unstable and capsize. All three subjects were ejected into the 33 degree water. They attempted to get back into the canoe and caused it to flood. The subjects decided they needed to swim to shore in order to survive. The owner made it to shore. He went to his garage to retrieve a small jon boat and went back out on the river to save the other two subjects. The owner made it to one of the subjects and was able to get him to shore. The third subject was last seen in the middle of the river near the swamped canoe and was seen going under the water just before the Sheriff's Department got to the area of the canoe attempting to save him. The subject in the middle of the canoe was seated on a plastic lawn chair placed in the canoe and there were only two life jackets on board. Neither of the life jackets were used or attempted to be used and were located in or near the swamped canoe when the Sheriff's Deputy got to the canoe. The investigation revealed the improper seating and high center of gravity in the canoe contributed to the instability of the canoe and the quick movement by the subject caused the canoe to capsize. The owner/operator was cited for insufficient number of PFDs, failure to display valid registration, and fishing without a valid license in possession.

Contributing Factors: Standing/Sitting in Inappropriate Position

Passenger/Skier Behavior

Alcohol Use

Failure to Wear Personal Floatation Device (PFD)

7. On March 26th, 2009, the victim advised his wife that he was going fishing. The victim launched his boat from Starved Rock State Park and navigated to the confluence of the Illinois and Vermillion Rivers. The victim entered the Vermillion River and travelled approximately 1.3 miles upriver where his boat became hung up on submerged rocks. He removed his shoes and sock and exited the boat in what is believed to be an attempt to dislodge the boat from the submerged rocks. It is believed that he then slipped off the rock or fell into a deep hole in the river and drowned. The victim was reported as not being able to swim. His body was recovered a short distance away. The primary cause of death was determined to be drowning.

Contributing Factors: Attempted to push the boat from the rock  
Could not swim  
Failure to Wear Personal Floatation Device (PFD)

8. On April 4<sup>th</sup>, 2009, while fishing on Rice Lake, the victim's line became tangled on a tree limb. After freeing the line, he stood up and lost his balance. He fell backwards into the water, causing the operator to fall overboard as well. The operator was able to re-enter the boat. The third individual onboard threw the bow line towards the victim unsuccessfully, and tried to dog paddle the boat to the victim. The victim surfaced twice before disappearing. His body was recovered approximately a hour later. Autopsy reports indicate the victim died from drowning.

Contributing Factors: Passenger/Skier Behavior  
Overloading  
Failure to Wear Personal Floatation Device (PFD)

9. On April 15<sup>th</sup>, 2009, a witnesses observed a boat with one individual aboard traveling south on Lake Lou Yaeger. A few moments later, they observed the boat traveling north and turning in circles with no one aboard. Search and rescue operations were immediately started and a ground search was also initiated. The victim's body was recovered several days later. The investigation indicated the victim had tied the steering wheel off with a line, placed the motor in forward gear (full throttle), and left the helm to remove the stern drain plug in an attempt to remove water from the hull. The victim would have been standing or leaning over when moving to the stern to remove the drain plug and would not have had the lanyard cutoff switch attached to his person. This action is a careless practice, but it is not believed to have caused his fall overboard. Preliminary coroner's report indicates that the victim had a heart condition that may have caused a severe angina attack causing him to fall overboard.

Contributing Factors: Sudden Medical Condition  
Failure to Wear Personal Floatation Device (PFD)

10. On June 28th, 2009, two subjects were boating on Senachwine Lake. The sailboat they were on capsized and both men fell overboard. The victim may have died from a cardiac arrhythmia and fell overboard causing the boat to capsize. It is also possible that while the victim was in the water he suffered a cardiac arrhythmia.

Contributing Factors: Sudden Medical Condition  
Weather  
Failure to Wear Personal Floatation Device (PFD)

11. On June 10<sup>th</sup>, 2009, the victim stated to a friend that he was going fishing on the Cook County Forest Preserve Pond. He left his truck at the friend's residence. Later that night, the friend noticed the victim had not returned and notified the authorities. Attempts to locate the victim were unsuccessful that night and the search resumed the next day. The victim's fishing equipment was found floating and the canoe was found capsized. A short time later, the body was recovered fully clothed and wearing a pair of hip boots. Autopsy reports indicate the victim drowned. The only other injury was a slight laceration to his head. The investigation concluded the canoe was an unstable platform. Any movement left or right of the center would have caused the canoe to become susceptible to capsizing. The victim is believed to have fallen overboard after the canoe he was fishing from capsized. The hip boots he was wearing likely restricted his ability to swim and prevented him from making it to shore. The victim was not wearing a lifejacket.

Contributing Factors: Standing/Sitting in Inappropriate Position  
Operator Inexperience  
Failure to Wear Personal Floatation Device (PFD)

12. On June 25<sup>th</sup>, 2009, during a day of rafting on the Vermillion River, three subjects failed navigating the bypass of a low head dam. The subjects went over the dam and became caught in the boil. Two of the victims escaped the boil of the low head dam; unfortunately, the third drowned. The two survivors were treated for hypothermia and released. The three occupants of the raft failed to adhere to safety instructions and to a sign advising paddlers to stay to the right side of the river for safe passage at the Buzzi Cement Plant Dam. This resulted in their raft becoming trapped in the recirculating waters of the dam. After entering the water due to a combination of their own will and because of being pushed out by water rushing into their raft (unclear), two of the occupants became trapped in the recirculating waters of the dam. One occupant is believed to have drowned after being forced downward multiple times by the water falling over the crest of the dam. All occupants had been consuming alcohol, which may have affected their ability to recognize the dangerous conditions surrounding the dam and to effectively navigate their raft to the safe passage area on the right side of the dam.

Contributing Factors: Alcohol Use  
Low head dam  
Operator(s) Inexperience behavior

13. On July 11<sup>th</sup>, 2009, two subjects were boating on Fox Lake. The passenger stated she left the boat to swim and the victim followed her. While they were swimming, the boat drifted away. The passenger was able to swim to the boat and climb aboard. She could not see the victim in the water. The passenger had a BAC of .18 and stated the victim had as much to drink or maybe more. The victim's body was recovered in about two feet of water southeast of the boat.

Contributing Factors: Alcohol Use  
Improper Anchoring  
Failure to Wear Personal Floatation Device (PFD)

14. On June 28<sup>th</sup>, 2009, the victim and one unknown male subject were onboard a 17 foot bass boat on the Calumet River. It was reported that the operator and passenger both fell overboard. They went underwater and disappeared. The operator's body was found floating down river by divers. The unknown subject has yet to be found. The investigation was unable to determine the contributing factor(s) of the men to fall overboard. The cause of death of the operator was determined to be drowning.

Contributing Factors: Unknown  
Failure to Wear Personal Floatation Device (PFD)

15. On July 8<sup>th</sup>, 2009, the victim was boating on Lake Sangchris. The investigation determined the victim fell overboard while conducting repairs on his motor. It is probable that while adjusting the carburetor, the victim was standing up and attempted to start the motor while in gear. The motor started at full throttle and caused him to fall overboard. The victim was not wearing a personal flotation device and had disabled the neutral safety switch, which allowed the motor to be started in gear and at full throttle. There was no lanyard cut off switch to disable the motor. The victim's body was recovered two days later.

Contributing Factors: Machinery failure, conducting repairs to the motor while on the water  
Starting in gear  
Disabled neutral safety switch  
Standing in boat, while starting in gear  
No lanyard to cut off switch to disable motor  
Failure to wear Personal Floatation Device

16. On July 28<sup>th</sup>, 2009, there were four subjects boating on Lake Lou Yeager. They were en route back to a marina and attempting to beat an approaching storm when the water became rough. As they exited a cove into the main body of the lake, they encountered rough waves generated by wind. They also were carrying miscellaneous equipment causing the boat to be overloaded. One passenger was seated in the front of the boat and was holding a portable generator. There was also a trolling motor (including foot remote), marine battery, fishing poles, and anchor secured inside the bow. The waves entered over the bow adding additional weight to the front of the boat (weight of water 8.34 lbs/gal). The additional weight caused the bow to become submerged and the forward momentum of the boat continued to drive the bow beneath the water. The passengers and victim were immediately pushed back by the oncoming water. Weight transfer within the boat from unsecured items, passenger movement, and oncoming water caused the boat to capsize to the starboard side. The passengers and victim entered the water as the boat capsized and partially sunk. The bottom of the outboard motor and only a small portion of the transom were exposed above the waterline. Two of the passengers swam to shore. One passenger wearing a life jacket was pushed away from the scene by wind and the victim subsequently became unresponsive and slipped beneath the waterline. The victim and passenger were recovered from the water and attempts to revive the victim were unsuccessful.

Contributing Factors: Overloading  
Weather  
Failure to Wear Personal Floatation Device (PFD)

17. On August 15<sup>th</sup>, 2009, a father and daughter were fishing on Sam Dale State Park Lake. The daughter stated that she and her father (victim) motored over to a spot to fish and dropped anchor approximately thirty feet from shore. She felt the boat start to rock and grabbed onto the sides of the boat. She looked back and all she saw was the bottom of her dad's shoes as he fell overboard. Neither she nor her father was wearing a life jacket at the time of the accident. She yelled for help and two nearby boats came to assist. One boat pulled the victim's boat to shore. The other boat operator dove into the water attempting to find the victim. The cause of death was determined to be drowning.

Contributing Factors: Sudden Medical Condition  
Failure to Wear Personal Floatation Device (PFD)

18. On August 26<sup>th</sup>, 2009, two subjects were competing on Rend Lake in a fishing tournament. During the tournament, the victim became unresponsive to questions from the passenger. However, the victim continued to fish. Approximately five minutes later, the victim put down his fishing pole and put up the trolling motor. He then took a step back and fell off the port side of the boat. He entered the water face first and head down. The passenger stated the victim's arms and feet did not raise and he went straight down into the water. The passenger jumped in attempt to rescue the victim. The victim was not wearing a PFD. The body was recovered face down in eight feet of water with both arms "locked" near his chest a few hours after the accident.

Contributing Factors: Unknown  
Failure to Wear Personal Floatation Device (PFD)

19. On September 3<sup>rd</sup>, 2009, two subjects were setting anchor behind a dike on the Mississippi River. While the operator was trying to set anchor, the victim had already thrown out his fishing poles and was fishing off the port side near the driver's seat. The operator stepped up on the bow to adjust the anchor, which appeared to be stuck in some brush. The operator pulled on the anchor causing the boat to rock towards the port side of the boat. The operator fell down on the bow of the boat facing aft. When he looked up, the operator saw the victim in the water hanging onto the port side with only his left arm. The victim's head was slumped on his left shoulder. The operator was attempting to pull the victim back into the boat when he fell overboard. After falling overboard, the operator was approximately twenty feet downstream of the victim. The victim was wearing a life jacket and thrashing around in the water. The operator swam back to the boat and retrieved a life jacket for himself. He swam back to the victim who was unconscious and face down in the water. The operator rolled the victim over and began swimming him to shore. The operator yelled for help for approximately thirty minutes before someone heard him to send help. The victim had a history of Parkinson's disease. The victim recently had a pacemaker installed and was having trouble with it.

Contributing Factors: Improper Anchoring  
Sudden Medical Condition  
Failure to Wear Personal Floatation Device (PFD)

## **Glossary of Boating Terminology**

**Airboat** - A boat propelled by an engine producing air thrust. This type of boat does not include ground effect vessels or air cushion vehicles (hovercraft).

**At anchor** - Held in place in the water by an anchor; includes “moored” to a buoy or anchored vessel and “dragging anchor”.

**Auxiliary Sail** - A sailboat also equipped with an engine.

**Cabin motorboat** - A motorboat equipped with accommodation spaces, i.e., bunks or berths.

**Canoe** - A small narrow boat, propelled by paddles. Canoes usually are pointed at both bow and stern and are normally open on top, but can be covered.

**Capsizing** - Overturning of a vessel.

**Carbon Monoxide Poisoning** - Death or injury resulting from an odorless, colorless gas generated from auxiliary boat equipment (stoves, heaters, refrigerators, generators, hot water heaters, etc.), another boat’s exhaust, or the exhaust of the vessel on which persons were either aboard or in close proximity.

**Careless/Reckless Operation** - A vessel is being operated carelessly or negligently when it endangers the life, limb or property of persons onboard or other vessels.

**Collision with fixed object** - The striking of any fixed object, above or below the surface of the water.

**Collision with floating object** - Collision with any waterborne object above or below the surface that is free to move with the tide, current, or wind, except another vessel.

**Collision with vessel** - Any striking together of two or more vessels, regardless of operation at time of the accident, is a collision.

**Congested Waters** - Where the body of water is either too small or narrow to safely accommodate the number of boats on it.

**Cruising** - Proceeding normally, unrestricted, with an absence of drastic rudder or engine changes.

**Documented vessel** - A vessel of five or more net tons owned by a citizen of the United States and used exclusively for pleasure with a valid marine document issued by the Coast Guard. Documented vessels are not numbered.

**Drifting** - Underway, but proceeding over the bottom without use of engines, oars or sails; being carried along only by the tide, current, or wind.

**Electrocution** - Death or injury resulting from an electrical current that comes in contact with water causing electrocution of the victim.

**Excessive Speed** - Speed above that which a reasonable and prudent person would have operated under the conditions that existed. It is not necessarily a speed in excess of a posted limit.

**Failure to vent** - Prior to starting the engine, failure to turn on the powered ventilation system that brings in “fresh air” and expels gasoline vapors from the engine compartment.

**Fall in Boat** - Any operator or passenger who slips, trips, or falls on board or within the vessel.

**Falls on Boat** - Any operator or passenger who impacts the vessel.

**Falls Overboard** - Any operator or passenger who falls off of the vessel.

**Fiberglass (plastic) hull** - Hulls of fiber-reinforced plastic. The laminate consists of two basic components, the reinforcing material (glass filaments) and the plastic or resin in which it is embedded.

**Fire/explosion (fuel)** - Accidental combustion of vessel fuel, liquids, including their vapors, or other substances such as wood.

**Fire/explosion (other)** - Accidental burning or explosion of any material onboard except vessel fuels or their vapors.

**Flooding/Swamping** - Filling with water, regardless of method of ingress, but retaining sufficient buoyancy to remain on the surface.

**Fueling** - Any stage of the fueling operation; primarily concerned with introduction of explosive or combustible vapors or liquids on board.

**Grounding** - Running aground of a vessel, striking or pounding on rocks, reefs, or shoals; stranding.

**Hazardous Waters** - Rapid tidal flows (the vertical movement of water) and/or currents (the horizontal flow of water) resulting in hazardous conditions in which to operate a boat.

**Houseboat** - A motorized vessel designed primarily with accommodation spaces with little or no foredeck or cockpit, with low freeboard and with a low length to beam ratio.

**Hull Failure** - Defect or failure of the structural body of a vessel (i.e., hull material, design, or construction) not including superstructure, masts, or rigging.

**Ignition of Spilled Fuel or Vapor** - Accidental combustion of vessel fuel, liquids, and/or their vapors.

**Improper anchoring** - Where a boat is either in the process of being anchored incorrectly or incorrectly held in place in the water by an anchor.

**Improper loading** - Loading, including weight shifting, of the vessel causing instability, limited maneuverability, or dangerously reduced freeboard.

**Improper lookout** - No proper watch; the failure of the operator to perceive danger because no one was serving as lookout or the person so serving failed in that regard. Every vessel shall at all times maintain a proper lookout by sight and hearing as well as by all available means appropriate in the prevailing circumstances and conditions so as to make a full appraisal of the situation and of the risk of collision.

**Inflatable** - A vessel constructed with its sides and bow made of flexible tubes containing pressurized gas. On smaller inflatables, the floor and hull beneath it is often flexible. On larger inflatables, the boat often has a rigid floor and solid hull capable of supporting a more powerful transom mounted outboard engine or even an inboard engine.

**Kayak** - A small boat with a cockpit that is propelled by a double-bladed paddle by a sitting paddler.

**Lack of or improper boat lights** - Insufficient and/or improper lights shown by a boat that indicate course, position, and occupation, such as fishing or towing.

**Machinery Failure** - Defect and/or failure in the machinery or material, design or construction, or components installed by the manufacturer involved in the mechanical propulsion of the boat (e.g., engine, transmission, fuel system, electric system, and steering system).

**Maneuvering** - Changing of course, speed, or similar boat handling action during which a high degree of alertness is required or the boat is imperiled because of the operation, i.e. docking, mooring, undocking, etc.

**Motorboat** - Any vessel equipped with propulsion machinery.

**Numbered vessel** - An undocumented vessel numbered by a state with an approved numbering system under Chapter 123 of title 46, U.S.C.

**Open Motorboat** - Craft of open construction specifically built for operating with a motor, including boats canopied or fitted with temporary partial shelters.

**Operator Inattention** - Failure on the part of the operator to pay attention to the vessel, its occupants, or the environment in which the vessel is operating.

**Operator Inexperience** - Lack of practical experience or knowledge in operating a vessel or, more particularly, the vessel involved in the accident.

**Outboard** - An engine not permanently affixed to the structure of the craft, regardless of the method or location used to mount the engine, e.g., motor wells, “kicker pits”, motor pockets, etc.

**Overloading** - Excessive loading of the vessel causing instability, limited maneuverability, dangerously reduced freeboard, etc.

**Passenger/Skier Behavior** - Behavior by any of the boats passengers as well as those being towed that interferes with the safe operation of a vessel.

**Personal Watercraft** - Craft designed to be operated by a person or persons sitting, standing or kneeling on the craft rather than within the confines of a hull.

**Pontoon Boat** - A boat consisting of a rigid structure connecting at least two parallel fore (front) and aft (back) rigid sealed buoyancy chambers.

**Restricted Vision** - A vessel operator's vision is said to be restricted when it is limited by a vessel's bow high trim, or by glare, sunlight, bright lights, a dirty windshield, spray, a canopy top, etc.

**Rowboat** - A open boat propelled by one or more persons using oars.

**Rules of the Road Infraction** - Violation of the statutory and regulatory rules governing the navigation of vessels.

**Sail (only)** - Any boat whose sole source of propulsion is the natural element (i.e., wind) or a boat designed or intended to be propelled primarily by sail, regardless of size or type.

**Sharp Turn** - An immediate or abrupt change in the boat's course of direction.

**Sinking** - Losing enough buoyancy to settle below the surface of the water.

**Skier Mishap** - Skier mishap is defined by persons (1) falling off their water-skis, (2) striking a fixed or submerged object, or by (3) becoming entangled or struck by the tow line. Also includes mishaps involving inner-tubes and other devices on which a person can be towed behind a boat.

**Standing/Sitting on gunwales, bow, and transom** - Standing/Sitting on the upper edge of the side of a boat, usually on a small projection above the deck; and/or standing/sitting on the most forward part of the boat; and/or standing/sitting on the back of the boat.

**Starting in Gear** - The boat's engine is started with the transmission in forward or reverse.

**Steel hull** - Hulls of sheet steel or steel alloy, not those with steel ribs and wood, canvas, or plastic hull coverings.

**Sterndrive** - An inboard/outboard engine system, with the engine inside the hull connected to an external lower unit containing a propeller. Steering is achieved by turning the lower unit.

**Struck by Boat** - A person is struck by a boat.

**Struck by Propeller/Propulsion Unit** - A person is struck by the propeller, propulsion unit, or steering machinery.

**Struck Submerged Object** - A boat's collision with any waterborne or fixed object that is below the surface of the water.

**Towing** - Engaged in towing any vessel or object, other than a person.

**Wake** - The track in the water of a moving boat; commonly used for the disturbance of the water (waves) resulting from the passage of the boat's hull.

**Weather** - As a contributing factor of an accident, "Weather" is supposed to signify a stormy or windy condition, usually connoting rough or high seas and dangerous operating conditions.

**Wood hull** - Hulls of plywood, molded plywood, wood planking, or any other wood fiber in its natural consistency, including those of wooden construction that have been "sheathed" with fiberglass or sheet metal.